



A



B

Figure 5. Photographs taken 7 weeks apart of the east end of Timbalier Island illustrating the severe erosion that occurred along the margin of Little Pass Timbalier during Hurricane Andrew: A) Before - taken July 9, 1992, and B) After - taken August 30, 1992.